





Commercial Kitchen Floor Coating

PROBLEM:

Kitchen required up-grade in equipment, the de-commissioning of existing equipment exposed many failings in the existing floor.

SOLUTION:

Remove exposed defects in the floor surface, patch repair the floor surface, particularly around drains, doorways etc. Apply new coatings of epoxy flooring with 100% solids.

PRODUCTS:

Sikadur 31, Sikafloor 261T epoxy coating system.

